

Rat Rig

01. Base Frame Assembly

Written By: Miguel Cruz




INTRODUCTION


Please note: This guide is based upon building a 750x750 StrongHold ONE CNC.

Measurements for the 750x1250 and 1250x1250 machine sizes are provided in the relevant steps.

It is **strongly recommended** to assemble the base frame on a known flat surface (such as a solid table, work surface or similar). Assembling the frame on a carpeted floor, or other non-flat surface, can cause the finished frame to not be square. This can cause issues with quality and performance.

Step 1 — Prepare the machine base extrusions & brackets

- 2x 1000mm 40120 Extrusion [1500mm for the StrongHold ONE 750x1250 or 1250x1250]
- 920mm 4040 Extrusion [1420mm for the StrongHold ONE 750x1250 or 1250x1250]
- 2x 864mm 4040 Extrusion [1364mm for the StrongHold ONE 1250x1250]
- 2x 412mm 4040 Extrusion [662mm for the StrongHold ONE 1250x1250]
- 16x 4040 Cast Corner Assemblies
- 4x 4040 Extruded Corners Assemblies for the spoil board


Step 2 — Assemble the front & rear 4040 extrusions

- 864mm 4040 Extrusion
- 4040 Cast Corner Assembly
- Install one corner assembly onto each end of the 4040 extrusion as shown. Tighten the M8x16 screw to secure them.
- Ensure the corner assemblies are flush and square with the ends of the extrusions after tightening the screws
- ① Repeat these instructions for the second 864mm 4040 extrusion

Step 3 — Assemble the middle 4040 extrusion



- 920mm 4040 Extrusion
- 4040 Cast Corner Assembly
- Install corner assemblies on to both sides of each end of the 4040 extrusions as shown. Tighten the M8x16 screw to secure them.
- Ensure the corner assemblies are flush and square with the ends of the extrusions after tightening the screws


Step 4 — Assemble the central frame support (x2)

- 412mm 4040 Extrusion
- 4040 Cast Corner Assembly
- Install corner assemblies on to both sides of each end of the 4040 extrusions as shown. Tighten the M8x16 screw to secure them.
- Ensure the corner assemblies are flush and square with the ends of the extrusions after tightening the screws

Step 5 — Assemble base frame ends (x2)




- Front / Back Assembly from Step 2
- Central Frame Support Assembly from Step 4
- Position the central frame support in the middle of the assembly from **Step 3**, as shown.
- Tighten the marked M8 cap head screws to secure the extrusions together
- Repeat these instructions for the second central frame support

Step 6 — Assemble the base frame - Part 1


- Middle Assembly from the previous step
- Front & Rear Assemblies from **Step 2**
- Position the three assemblies as shown
- Ensure that the ends of all three 4080 extrusions are aligned
- Tighten the marked M8 cap head screws to secure the extrusions together

Step 7 — Assemble the base frame - Part 2



- 1000mm 40120 Extrusion
- Align each of the 40120 extrusions as shown
- Ensure that the ends of both 40120 extrusions are aligned with the ends of the frame
- Tighten the marked M8 Cap Head Screws to secure the base together

Step 8 — Prepare the base frame end plate parts



- 2x Rat Rig StrongHold ONE CNC - Motor Plate
- 2x Rat Rig StrongHold ONE CNC - Idler Plate
- 12x M12 Washer
- 12x M12x45 Cap Head Screw
- 4x M8x22 Cap Head Screw
- 4x M8 Washer
- 4x 4040 Drop-in T-Nut - M8

ⓘ The main difference between the motor and idler plates is the Stepper motor mount holes.

Step 9 — Assemble the front idler plates



- Rat Rig StrongHold ONE CNC - Idler Plate
- M8 Washer
- M8x22 Cap Head Screw
- 4040 Drop-in T-Nut - M8
- Make sure the counterbore for the bearing is on the same side as the T-Nut.
- ☑ Loosely thread a 4040 T-Nut on to each of the M8x22 screws. Do not tighten them at this point.
- Repeat these instructions for the second idler plate.
- ⓘ Set these assemblies aside until **Steps 11 & 12**

Step 10 — Assemble the rear motor plates



● Rat Rig StrongHold ONE CNC - Motor Plate

● M8 Washer


● M8x22 Cap Head Screw

● 4040 Drop-in T-Nut - M8

★ Loosely thread a 4040 T-Nut onto each of the M8x22 screws. Do not tighten them at this point.


● Repeat these instructions for the second motor plate.

i Set these assemblies aside until **Steps 16 & 17**


Step 11 — Install the front left idler plate

- Left idler plate Assembly from Step 9
 - Align the idler plate assembly with the base frame as shown
 - M12 Washer
 - M12x45 Cap Head Screw
- i** Place an M12 Washer on to each M12x45 Cap Head screw and loosely screw them through the plate and in to the extrusion.
- !** Do not fully tighten any of the M12 or M8 Cap Head Screws at this point

Step 12 — Install the front right idler plate




- Right idler plate assembly from Step 9
 - Align the idler plate assembly with the base frame as shown
 - M12 Washer
 - M12x45 Cap Head Screw
- i** Place an M12 Washer on to each M12x45 Cap Head screw and loosely screw them through the plate and in to the extrusion.
- !** Do not fully tighten any of the M12 or M8 Cap Head Screws at this point

Step 13 — Install the rear right motor plate


- Right motor plate assembly from Step 10
 - Align the motor plate assembly with the base frame as shown
 - M12 Washer
 - M12x45 Cap Head Screw
- i** Place an M12 Washer on to each M12x45 Cap Head screw and loosely screw them through the plate and in to the extrusion.
- !** Do not fully tighten any of the M12 or M8 Cap Head Screws at this point

Step 14 — Install the rear left motor plate




- Left motor plate assembly from Step 10
 - Align the motor plate assembly with the base frame as shown
 - M12 Washer
 - M12x45 Cap Head Screw
- i** Place an M12 Washer on to each M12x45 Cap Head screw and loosely screw them through the plate and in to the extrusion.

! Do not fully tighten any of the M12 or M8 Cap Head Screws at this point

Step 15 — Install the spoil board brackets

- 4040 extruded corner assembly (For the spoil board)
- Position the 4040 extruded corner assembly in the middle of the extrusion gap as shown
- The displayed measurement should be:
 - ① 220mm for StrongHold ONE 750x750
 - ① 345mm for StrongHold ONE 750x1250 or 1250x1250
- Ensure that the top of the extruded corner assembly is flush with the top of the 4040 extrusions.
- Fully tighten the M8 cap head screw to secure the extruded corner assembly to the frame
- Repeat the above instructions for the remaining 3 extruded corner assemblies

Step 16 — Ensure the base frame is square




- i** Before continuing with the assembly, the frame must be squared and all screws full tightened

 - Using an engineers square, check that the side 40120 extrusions are square to the extrusions forming the base
- i** On each side, tighten all of the following screws whilst continuing to check that the side extrusion remain square with the base:


 - 4x M8x16 within the cast corners connected to the base
 - 6x M12x45 on the motor and idler plates
 - 2x M8x22 on the motor and idler plates
- i** Once one side is fully secured and squared, proceed to repeat the process on the other side
- i** After tightening all screws, check the entire frame once more for squareness. Correcting any issues now is easier than once the assembly is complete!

Step 17 — Prepare the Y-axis linear rails



- 2x 1000mm HG15 Linear Rail with 2x Carriages
 - ⓘ 1500mm for a 750x1250 or 1250x1250 machine
- 34x M4x20 Cap Head Screw
 - ⓘ 50x for a 750x1250 or 1250x1250 machine
- 34x 4040 Drop-in T-Nut - M4
 - ⓘ 50x for a 750x1250 or 1250x1250 machine
- 2x align_40120_hg15 Printed Part

Step 18 — Unpack and prepare two HG15 linear rails



⚠ The linear rails are supplied with a protective oil coating on them. It is **strongly recommended** to prepare

your work surface with paper towels and to wear disposable gloves.

- Paper Towels


- Linear Rail

① Carefully open one end of the linear rail packaging and remove the rail. Place the rail upon the paper towels and dispose of the packaging

⚠ The oil on the rails protects them from rusting. Make sure not to remove all of the original oil during preparation.


⚠ The linear rail carriages are not interchangeable. Do not try to use a carriage on a different linear rail than the one it was supplied with.

Step 19 — Inspect & test the HG15 linear rails



- With the rail still on the absorbent paper towels, carefully and slowly move the carriage from one end of the rail to the other
 - ① Both carriages should move smoothly over the entire length of the rail
- ⚠ Small changes in resistance are normal, but the carriage becoming very hard to push, or binding completely are not
- Repeat the previous test whilst applying a small amount of force downwards on the carriage
 - ① The carriage will likely travel more smoothly when applying a downwards force, this is normal
- Repeat the process to check the second carriage on the rail
- ⚠ If the carriage does not move smoothly, or binds completely, refer to the [Linear Rail Troubleshooting Guide](#)

Step 20 — Assemble the HG15 linear rails



⚠ Do not allow the linear rail carriages to leave the end of the rail at any point

- HG15 Linear Rail
- Insert an M4x20 cap head screw into each of the holes on the linear rail
- Loosely thread a 4040 T-Nut on to each of the M4x20 screws
- ① Repeat these instructions for the second linear rail

Step 21 — Install the HG15 linear rails - Part 1


- StrongHold ONE base assembly from **Step 16**
- HG15 Linear Rail assembly from **Step 20**
- Install the two HG15 40120 alignment tools as shown, this will make sure the linear rail is positioned correctly
- Tighten every other M4x20 screw, starting from one end
- Tighten the remaining M4x20 screws, starting from the same end as before
- Remove the HG15 40120 alignment tools

Step 22 — Install the HG15 linear rails - Part 2



- Repeat the instructions in the previous step to install the second HG15 linear rail to the base assembly


Step 23 — Prepare the Y - axis lead screw parts




- 2x 1057mm TR8x8 Lead Screw (1557mm for a 750x1250 or 1250x1250 machine)
- 2x Lead Screw Tensioning Nut
- 4x Thrust Bearing F8-16M
- 4x 688ZZ Ball Bearing
- 6x Lock Collar 8mm
- 4x Nut Block for TR8x8
- 8x M5 Nylon Locking Hex Nut
- 4x Precision Shim 12x8x1mm

Step 24 — Prepare the nut blocks (x4)

- Nut Block for TR8x8
- M5 Nylon Locking Hex Nut
- Insert the M5 Locking Hex Nut into the Nut Block

Step 25 — Install the rear right lead screw ball bearing


- 688ZZ Ball bearing
- Push the ball bearing against the slot on the inner side of the plate.
- Push the 688ZZ ball bearings against the slots on the inner sides of the plates.

Step 26 — Install the Y-Axis Lead Screw - Part 1

⚠ While performing this step, make sure to support the Lead Screw to prevent it from bending

- Lead Screw
- Insert the Lead Screw from the back of the assembly through the hole in the ball bearing
- Precision Shim 12x8x1mm
 - ① Slide the Precision Shim on to the Lead Screw.
- Lock Collar
 - ① Slide the Lock Collar on to the Lead Screw.

⚠ Do not tighten the screw on the Lock Collar yet.

Step 27 — Install the Y-Axis Lead Screw - Part 2

- Nut Block for TR8x8
- Screw the Lead Screw through both Nut Blocks.
- ① Make sure the M5 Nylon Locking Hex Nuts on the Nut Blocks are facing the 40120 extrusion

Step 28 — Install the Y-Axis Lead Screw - Part 3

- Lock Collar 8mm
 - ① Slide the Lock Collar on to the Lead Screw
 - ⚠ Do not tighten the screw on the Lock Collar yet.
- Precision Shim 12x8x1mm
 - ① Slide the Lock Collar on to the Lead Screw

Step 29 — Install the Y-Axis Lead Screw - Part 4




- Pull the Lead screw through the ball bearing inserted on the idler plate.

Step 30 — Attach the Tensioner Nut



- Thrust Bearing F8-16M
- Tensioner Nut
- ⓘ Install the Thrust Bearing on to the exposed end of the Lead Screw as shown
- ⓘ Screw the Tensioning Nut on to the end of the lead screw
- ⚠ Do not tighten the screw on the Tensioner Nut yet.

Step 31 — Install the remaining lead screw components

- Thrust Bearing F8-16M
- Lock Collar
- ⚠ Do not tighten the screw on the Lock Collar yet.
- ⓘ Slide the Thrust Bearing and Lock Collar on to the Lead Screw as shown.

Step 32 — Assemble the other Y - axis Lead Screw



- Repeat **Steps 27 through 32** to assemble the remaining Lead Screw
- ☑ The Lead Screws will be fully tensioned and adjusted later in the assembly process

Step 33 — Next guide



- Continue with the next guide: [02. X-Axis Gantry Assembly](#)