




Rat Rig

03. Z-Axis Assembly


Written By: Miguel Cruz




Step 1 — Prepare the Z - Axis Parts


- 250mm 40120 Extrusion
- Rat Rig StrongHold ONE CNC Bottom Plate
- Rat Rig StrongHold ONE CNC TopPlate
- 3x M12x45 Cap Head Screw
- 3x M12x25 Countersunk Screw
- 3x M12 Washers

Step 2 — Install the Bottom Plate




- 250mm 40120 extrusion
 - Rat Rig StrongHold ONE CNC Bottom Plate
 - 3x M12x25 Countersunk Screw
-  Tighten the screws on the Bottom Z Plate

Step 3 — Install the Top Plate



- Assembly from previous Step
- Rat Rig StrongHold ONE CNC Top Plate
- 3x M12 Washers
- 3x M12x45 Cap Head Screw
- ⓘ Tighten the screws on the Top Z Plate

Step 4 — Prepare the Z-Axis MGN15 Linear Rails




- 2x 250mm MGN15 Linear Rail with 2x Carriages
- 10x M3x16 Cap Head Screw
- 10x 4040 Drop-in T-Nut - M4
- Leave the holes on the ends empty

✦ Prepare the Linear Rails as detailed in **Step 6** of the X-Axis Gantry Assembly Guide

- Insert an M3x16 Cap Head Screw into each of the holes on the linear rail and loosely thread a 4040 Drop-in T-Nut
- ① Repeat these instructions for the second linear rail



⚠ The linear rail carriages are not interchangeable. Do not try to use a carriage on a different linear rail than the one it was supplied with.

Step 5 — Install the MGN15 Linear Rails - Part 1



- Assembly from **Step 3**
- Linear Rail assembly from the previous step
- Install the MGN15 40120 alignment tool as shown, this will make sure the linear rail is positioned correctly
- Tighten the screw next to the alignment tool
- ⓘ Repeat the steps to tighten the screw on the other end of the rail
- ⚙ Tighten the remaining screws


Step 6 — Install the MGN15 Linear Rails - Part 2



- MGN15 linear rail

i Place the linear rail on to the 40120 extrusion as shown, do not tighten any of the screws at this point

Step 7 — Prepare the XZ Joiner Plate





- Rat Rig StrongHold ONE CNC XZ Joiner Plate
- 4x M5x16 Low Profile Cap Head Screw
- 2x Nut Block for TR8x8
- 4x M5 Nylon Locking Hex Nut
- ☒ Repeat **Steps 9 and 10** to assemble another XZ plate

Step 8 — Install the XZ joiner plate - Part 1


- Assembly from previous step
- XZ Plate assembly from previous step

⚠ Make sure the Nut Blocks face are facing the assembly, and the threads are oriented accordingly to the linear rails


- 16x M3x8 Cap Head Screw
- ① Install an M3x8 screw through each hole in the plate, and into the MGN15 linear rail carriage below, lightly tighten them

Step 9 — Install the XZ joiner plate - Part 2


- Push the XZ Plate to the one side
- Tighten the M3x16 screw closest to the XZ plate
- ⓘ Repeat the Steps with the Plate pushed to the opposite side
- ⚠ If the Z-axis binds or becomes tight, check that the lower rail is aligned correctly. Loosening the screws securing the lower rail to the 40120 extrusion and repeat the steps above.
- ⓘ Do not overtighten the screws as it can cause the axis to bind.

Step 10 — Install the XZ joiner plate - Part 3


- Remove the XZ Plate
- Tighten the remaining screws on the linear rail
- Move the carriages to access the screws underneath them
- Reinstall the XZ plate and tighten the screws on it

Step 11 — Install the top lead screw ball bearing



- 688ZZ Ball bearing
- Push the ball bearing against the slot on the inner side of the plate.

Step 12 — Install the Bottom lead screw ball bearing


- 688ZZ Ball bearing
- Push the ball bearing against the slot on the inner side of the plate.

Step 13 — Prepare the Z - Axis Lead Screw Parts


- 281mm TR8x8 Lead Screw
- 2x Precision Shim 12x8x1mm
- Thrust Bearing F8-16M
- 2x Lock Collar 8mm
- 2x 688ZZ Ball Bearing

Step 14 — Install the Z - Axis Lead Screw - Part 1

- Insert the Lead Screw through the hole in the ball bearing

Step 15 — Install the Z - Axis Lead Screw - Part 2

- Precision Shim
 - Lock Collar
 - Slide the components into the Lead Screw
- ⚠ Do not tighten the screw on the Lock Collar yet.

Step 16 — Install the Z - Axis Lead Screw - Part 3

- Thread the lead Screw in to the Nut Blocks on the XZ Plate and push the assembly
- Lock Collar
- Precision Shim
- Push the exposed end of the Lead Screw through the hole in the ball bearing
- Tighten the Screws on the Lock Collars to avoid the lead screw from falling in the next steps

Step 17 — Install the Thrust Bearing



- Install the Thrust Bearing F8-16M on to the Lead Screw

⚠ Be careful that the bearing does not fall off whilst this assembly is set aside

Step 18 — Next guide



- Continue with the next guide: [04. Z-Axis and Steppers Installation](#)